Microsemi Corporation

February 9, 2017

Customer Notification No: CN17002

Customer Advisory Notice (CAN)

Subject: Update to Libero FlexLM daemons v11.14.0.0 for Libero server-based floating licenses, and discontinued support for Libero Platinum floating license on Solaris platform

Description

CN17002 is issued based on the vulnerability note VU#485744 published by CERT Software Engineering Institute. Flexera software has confirmed about this vulnerability note, and reported that the bug can be leveraged to gain code execution. Microsemi has released Libero FlexLM daemons v11.14.0.0 to address this vulnerability. This CN recommends that the version of Libero FlexLM daemons, lmgrd/actlmgrd be updated from v11.12.1.0 or earlier to v11.14.0.0.

For backward compatibility, Libero FlexLM daemons v11.14.0.0 will continue to work with existing Libero installations up to Libero SoC v11.7. The Libero FlexLM v11.14.0.0 bundled packages are available on the Microsemi website at License Server Daemons.

The following table lists the latest FlexLM versions that are available for various platforms:

Platform	lmgrd/lmutil/lmhostid	actlmgrd	snpslmd	synplctyd	mgcld	syncad
Windows Daemons	v11.14.0.1	v11.14.0.1	v11.13.1.2	v10.8.2.1	11.13.1.2	6.1c
Linux Daemons	v11.14.0.1	v11.14.0.1	v11.13.1.2	v10.8.2.1	11.13.1.2	6.1g
Solaris Daemons	v11.14.0.0	v11.4.100.0	v11.13.1.2	v10.8.2.1	11.13.1.2	6.1c

Libero FlexLM daemons v11.14.0.0 were shipped with the Libero SoC v11.7 SP2 release. Starting with Libero SoC v11.8, the FlexLM v11.14.0.0 daemons should be used. If the FlexLM version is not updated, the following error is displayed when Libero SoC v11.8 is accessed.

This CN also notifies that Microsemi will stop supporting Solaris Platinum floating license effective January 2017. Microsemi will continue to support the Solaris Standalone floating license. The current Solaris FlexLM version for Microsemi vendor daemons is 11.4 and there are no future plans to update the version of the vendor daemons.

Note: Existing users working on Solaris Platinum floating license must migrate to Windows or Linux Platinum floating license on expiry of the current license.

Contact Information:

For more information, contact Microsemi's Technical Support at soc_tech@microsemi.com**.**

To purchase a license, contact your local Microsemi sales representative**.**

Regards,

Microsemi Corporation

Customer Notice (CN) or Customer Advisory Notice (CAN) are confidential and proprietary information of Microsemi and is intended only for distribution by Microsemi to its customers, for customers' use only. It must not be copied or provided to any third party without Microsemi's prior written consent.

About Microsemi
Microsemi Corporation (Nasdaq: MSCC) offers a comprehensive portfolio of semiconductor and system solutions for aerospace & defense, communications, data center and industrial markets. Products include high-performance and radiation-hardened analog mixed-signal integrated circuits, FPGAs, SoCs and ASICs; power management products; timing and synchronization devices and precise time solutions, setting the world's standard for time; voice processing devices; RF solutions; discrete components; enterprise storage and communication solutions; security technologies and scalable anti-tamper products; Ethernet solutions; Power-over-Ethernet ICs and midspans; as well as custom design capabilities and services. Microsemi is headquartered in Aliso Viejo, California, and has approximately 4,800 employees globally. Learn more at www.microsemi.com.