

## IIoT Product Change Notice


The change will be applied on the ULI-234TE (BB-485OPDRI-PH). If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.


**Note: The ordering process has not been changed. Customers should continue to order model number BB-485OPDRI-PH.**

- Reason for the Change:** Branding and UL File Number change.
- Affected Products:** ULI-234TE (BB-485OPDRI-PH)
- Impact on Application:** No change to form, fit, or function.

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	No
Impact on Environment Characteristics	No
Impact on System Certifications	<b>Yes – UL File Number is changing from E245458 to E337172</b>
Physical Outlook Change	<b>Yes</b>
Ordering P/N Change	No
Cut-in Implement	Component Running Change

### 4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
ULI-234TE BB-485OPDRI-PH	20BB250- 10713-00	1990039136T010 1990039139T010	Label	<p><b>Old name plate</b></p>  <p><b>New name plate</b></p> 	Branding and UL File Number

**5. Implementation & Schedule of the Change(s):**

Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
ULI-234TE (BB-485OPDRU-PH)	ECOM-196529	12/15/2022	Running Change	Update name plate and UL File Number

\*Note: Cut-in progress depends on factory production schedule.

\*\* Note: The ordering process has not been changed. Customers should continue to order model number BB-485DRCI-PH

**Contact Windows**

PM	Brian Foster / <a href="mailto:brian.foster@advantech.com">brian.foster@advantech.com</a>
AE	N/A